PRC Environmental Management, Inc. 233 North Michigan Avenue Suite 1621 Chicago, IL 60601 312-856-8700 Fax 312-938-0118



FOCUSED SITE INSPECTION PRIORITIZATION SITE EVALUATION REPORT

OHIO POWER COMPANY, PHILO PLANT PHILO, OHIO

EPA IDENTIFICATION NO. OHD 980 42 3 3 4 7

Prepared for

U.S. ENVIRONMENTAL PROTECTION AGENCY

Site Assessment Section 77 West Jackson Boulevard Chicago, IL 60604

Date Prepared : May 3, 1995

EPA Region : 5

 Contract No.
 :
 68-W8-0084

 Work Assignment No.
 :
 35-5JZZ

 PRC Project No.
 :
 030-0035101

Prepared by : PRC Environmental Management, Inc.

(Jeff Leto)

PRC Project Manager : Christopher Scott
Telephone No. : 312/856-8700
EPA Work Assignment Manager : Jeanne Griffin
Telephone No. : 312/886-3007

contains recycled fiber and is recyclable

CONTENTS

Section		$oldsymbol{I}$	age					
1.0	INTRO	DDUCTION	1					
2.0	SITE DESCRIPTION AND HISTORY							
3.0	PREVIOUS INVESTIGATIONS							
4.0	MIGRA	ATION AND EXPOSURE PATHWAYS	6					
	4.1	GROUNDWATER MIGRATION PATHWAY	6					
		4.1.1 Geology and Soils	7					
	4.2	SURFACE WATER MIGRATION PATHWAY	8					
		4.2.1 Migration Route						
	4.3	SOIL EXPOSURE PATHWAY	9					
	4.4	AIR MIGRATION PATHWAY	9					
5.0	SUMM	IARY	10					
REFER	ENCES	3	11					
Append	l <u>ix</u>							
SITE R	ECONN	NAISSANCE PHOTOGRAPHS						
Attachr	<u>nent</u>							
A	SITE INVESTIGATION SOIL AND SEDIMENT SAMPLING LOCATIONS AND ANALYTICAL RESULTS							
В	CONTRACT LABORATORY PROGRAM CONTRACT-REQUIRED DETECTION LIMITS							
С	AREA WELL LOGS							

FIGURES

<u>Figure</u>	<u>. </u>	age
1	SITE LOCATION	2
2	SITE LAYOUT	5


1.0 INTRODUCTION

Under Contract No. 68-W8-0084, Work Assignment No. 35-5JZZ, PRC Environmental Management, Inc. (PRC), has evaluated the Ohio Power Company, Philo Plant (Philo Plant), site in Philo, Muskingum County, Ohio, as a potential candidate for the National Priorities List (NPL) and has prepared this site evaluation report. Using the Hazard Ranking System (HRS), PRC performed focused site inspection prioritization (FSIP) activities for the site to determine whether, or to what extent, it poses a threat to human health and the environment. This report presents the results of PRC's evaluation and summarizes the site conditions and targets pertinent to the migration and exposure pathways associated with the site. Information was obtained from preliminary assessment (PA) and screening site inspection (SSI) reports; U.S. Environmental Protection Agency (EPA) files; Ohio Environmental Protection Agency (OEPA) files; and a site reconnaissance conducted by PRC on February 22, 1995.

This report has five sections, including this introduction. Section 2.0 describes the site and provides a brief site history. Section 3.0 provides information about previous investigations conducted at the site. Section 4.0 provides information about the four migration and exposure pathways (groundwater migration, surface water migration, soil exposure, and air migration) that can be scored. Section 5.0 summarizes conditions at the site. References used in the preparation of this report are listed at the end of the text. In addition, the appendix to this report contains photographs taken during the site reconnaissance.

2.0 SITE DESCRIPTION AND HISTORY

The Philo Plant site is an inactive, coal fired electrical power plant that was operated by the Ohio Power Company from October 1924 until the plant closed in May 1975 (Ohio Power Company 1975). The plant occupied 114.7 acres immediately east of the Town of Philo on the Muskingum River in Philo, Ohio. The Philo Plant site coordinates are 39°51'49" N latitude and 81°54'19" W longitude (USGS 1975a). The site's location is shown in Figure 1. The site is bordered to the east and the north by the Muskingum River, to the west by residences, and to the south by Duncan Run. A lock and dam is located approximately 1,300 feet northeast of the site on the Muskingum River



(USGS 1975a). After the plant closed, all buildings were demolished and removed. Since 1975, the site has remained vacant except for a small electrical substation that the Ohio Power Company operates (E&E 1991). The Ohio Power Company still owns the site. Site land use before 1924 is unknown. Until 1990, the site was relatively devoid of vegetation. Some time during 1990, the site was seeded (PRC 1995c).

The Philo Plant site formerly consisted of six power generating turbines capable of producing 33 to 100 megawatts of electricity (OEPA 1987). Temperature control of the power generating system was maintained with cooling water from the Muskingum River. Cooling water was brought into the Philo Plant site using a subsurface cooling water influent canal. This underground canal extends south from 500 feet north of the dam to midway through the site (E&E 1991). After use, the water was discharged back into the Muskingum River at two outfall locations located east of the electrical substation (see Photograph No. 1). Waste fly ash and bottom ash produced from burning coal were mixed with water to form a slurry. The slurry was then placed in one of the two surface impoundments located south of the electrical substation (see Photographs No. 2 and 3). Only one surface impoundment was operated at a time. The slurry was allowed to settle in the surface impoundments. When one surface impoundment was filled with ash, the second was used while the first was drained and dredged.

The sludge in the surface impoundments was then placed in the ash disposal area occupying 30 acres in the southern portion of the site. The eastern side of the ash disposal area is bermed. Water from the ash disposal area drained to the Muskingum River through an outfall located on the southeast side of the site. Information regarding ultimate disposal of the sludge is unavailable. Supernatant water drained from the surface impoundments into Clearwater Pond (see Photograph No. 4). Water from Clearwater Pond was then discharged to the Muskingum River through a National Pollutant Discharge Elimination System (NPDES) permitted outfall (PRC 1995c). Discharge from Clearwater Pond was regulated under NPDES Permit No. B 004 *AD from 1971 until it was revoked in 1981, after the Philo Plant site had closed (OEPA 1981). No other information regarding the NPDES permit is available. The two surface impoundments used to store waste fly ash and bottom ash and Clearwater Pond occupy a total of approximately 2.6 acres.

The site also contained two coal piles located near the railroad tracks where the coal was unloaded from freight cars. Both areas still contain substantial amounts of residual coal (see Photographs No. 5


and 6). Two debris piles are also located on site. The debris piles apparently consist mostly of bricks from the former buildings. One debris pile is located south of the former plant location, and the second is located west of the ash disposal area (E&E 1991). A site layout is presented in Figure 2.

3.0 PREVIOUS INVESTIGATIONS

Initial regulatory activity began at the Philo Plant in June 1971 when the Ohio Power Company filed for a NPDES permit to regulate surface impoundment discharge into the Muskingum River (OEPA 1981). OEPA conducted a preliminary assessment (PA) for the site in 1987 (OEPA 1987). After the PA, the EPA Field Investigation Team (FIT) conducted an SSI at the site on February 20 and 21, 1990 (E&E 1991).

During the SSI, five surface soil samples, three sediment samples, one background soil sample (S9), and one background sediment sample (S10) were collected approximately 0.5 mile west of the Philo Plant site. Sediment sample S10 was collected from the Muskingum River. Soil samples S1 and S2 were collected near the north surface impoundment. Soil sample S3 was collected near the southern surface impoundment. Soil sample S4 was collected south of Clearwater Pond. Soil sample S5 was collected from the ash disposal area. Sediment samples S6, S7, and S8 were collected near the west bank of the Muskingum River. Sample S6 was collected downstream of the NPDES-permitted outfall. Sample S7 was collected near the southern cooling water outfall. Sample S8 was collected approximately 2,200 feet upstream of the northernmost outfall (E&E 1991). Analytical results and sampling locations are presented in Attachment A.

Analytical results from the above samples show contamination in both soil and sediment. No volatile organic compounds (VOC) or semivolatile organic compounds (SVOC) were detected in the background samples. Methylene chloride was detected above the contract-required detection limit (CRDL), which are presented in Attachment B, required under the contract laboratory program (CLP) in soil samples collected near the surface impoundments and from the ash disposal area. Tetrachloroethene was detected above CRDLs in on-site soil samples collected near the surface.



impoundments. Methylene chloride was also detected above CRDLs in on-site sediment samples. Naphthalene, 2-methylnaphthalene, phenanthrene, fluoranthene, pyrene, benzo(a)anthracene, chrysene, and benzo(b)fluoranthene were detected above CRDLs in the on-site soil samples collected near the surface impoundments. No SVOCs were detected above CRDLs in the on-site sediment samples. Aluminum, arsenic, beryllium, thallium, and mercury were detected in on-site soil samples collected near the surface impoundments and from the ash disposal area at concentrations significantly above background concentrations. Silver was also detected in soil samples collected near the surface impoundments at concentrations significantly above background concentrations. Antimony, mercury, and silver were also detected in sediment samples collected from near the site at concentrations significantly above background concentrations significantly above background concentrations

4.0 MIGRATION AND EXPOSURE PATHWAYS

This section describes the four migration and exposure pathways associated with the Philo Plant site. Section 4.1 discusses the groundwater migration pathway; Section 4.2 discusses the surface water migration pathway; Section 4.3 discusses the soil exposure pathway; and Section 4.4 discusses the air migration pathway.

4.1 GROUNDWATER MIGRATION PATHWAY

This section discusses geology and soils, groundwater releases, and targets associated with the groundwater migration pathway at the site.

4.1.1 Geology and Soils

The Philo Plant site is located on a point bar in the flood plain of the Muskingum River. Soils in this area are characterized by alternating layers of silt, sand, and gravel deposits (E&E 1991). Bedrock in the area is present at 60 feet below ground surface (bgs) (OEPA 1987). The bedrock consists of Pennsylvanian Period sandstone and shale with some limestone and coal beds (E&E 1991). Because of the site's nearness to the Muskingum River, the river probably has a significant influence on groundwater flow direction. It is therefore assumed that groundwater at the site flows east to southeast toward the river. The depth to the shallowest aquifer under the site is unknown. The SSI report states

that Clearwater Pond was inundated with water during March 1991 (E&E 1991). It is therefore assumed that the groundwater elevation near Clearwater Pond is close to the ground surface because the pond is located on well drained soils with high infiltration rates characteristic of point bars. According to well logs from the area, drinking water is obtained from sand and gravel deposits at approximately 21 feet bgs. Attachment C presents a copy of area well log information from the Ohio Department of Natural Resources and U.S. Department of the Interior.

4.1.2 Groundwater Releases

No releases of hazardous substances to groundwater have been documented at the Philo Plant site; however, the potential for hazardous substances to migrate from contaminated soils to groundwater exists. Both Clearwater Pond and the two surface impoundments are unlined and had no leachate collection systems (OEPA 1987). During the 1990 SSI, four soil samples collected near both areas contained elevated levels of organic compounds and metals (E&E 1991). Because one sample collected from the ash disposal area contained elevated levels of VOCs and metals, the potential for a release of hazardous substances to groundwater from this area also exists.

4.1.3 Targets

The Town of Philo is located immediately west of the site. Approximately 1,000 Philo residents are supplied with drinking water from two municipal wells located approximately 0.25 mile south of the Philo Plant site (PRC 1995d). East of the Philo Plant site on the opposite side of the Muskingum River is the Town of Duncan Falls. Duncan Falls has a population of approximately 6,400 people who are supplied by two municipal wells located 0.5 mile northwest of the Philo Plant site (PRC 1995e). It is unlikely that these wells are affected by Philo Plant site contamination because the Muskingum River should act as a hydraulic barrier. The municipal wells are screened at approximately 65 feet bgs in sand and gravel. In addition to municipal wells, approximately 1,388 people within a 4-mile radius of the Philo Plant site use private wells as a source of potable water (Frost 1995).

4.2 SURFACE WATER MIGRATION PATHWAY

This section discusses the migration route, surface water releases, and targets associated with the surface water migration pathway at the site.

4.2.1 Migration Route

Surface soil and sediment contamination associated with the Philo Plant site could potentially migrate to the Muskingum River as a result of heavy precipitation or flooding. The Muskingum River is the only surface water body that can potentially receive hazardous substances from the site. The Philo Plant site is located in a naturally occurring, 100-year flood plain of the Muskingum River (FEMA 1988). The river has an average flow rate of 9,000 to 10,000 cubic feet per second and contains many locks and dams that allow some control of its flow rate, decreasing the potential for the river to flood (USGS 1992).

The surface impoundments can potentially release contaminants to the Muskingum River. Soil samples collected near the surface impoundments contained concentrations of VOCs, SVOCs, and metals at levels significantly above background concentrations (E&E 1991). The surface impoundments frequently discharged potentially contaminated wastewater that was used to treat fly and bottom ash into Clearwater Pond, which discharged the wastewater into the Muskingum River through a NPDES-permitted outfall.

A potential also exists for contaminants from the ash disposal area to be released to the surface water migration pathway. One soil sample collected from this area during the 1990 SSI was contaminated with elevated levels of VOCs and metals (E&E 1991). The ash disposal area is separated from the Muskingum River by a large berm. An outfall pipe on the east side of the berm appears to drain the disposal area and discharge directly into the river.

4.2.2 Surface Water Releases

During the 1990 SSI, three sediment samples were collected near two Philo Plant site outfalls. All three samples contained elevated levels of VOCs and metals. Based on analytical results from samples

collected on or near the site, a release of methylene chloride, mercury, and silver has occurred to the Muskingum River (E&E 1991). These compounds were detected at levels significantly above background levels in both on-site soil and sediment samples.

4.2.3 Targets

No drinking water intakes are located within 15 downstream miles of the Philo Plant site. The Muskingum River is used for recreational fishing and boating (PRC 1995b). An estimated 14,874 pounds of fish are caught within 15 miles downriver of the site and consumed annually (ODNR 1995). Between 1 and 2 linear miles of wetland habitat exist within 15 miles downriver of the site (DOI 1975). No threatened or endangered species or surface water intakes are currently known to exist within 15 miles downriver from the site (DOI 1994 and PRC 1995a).

4.3 SOIL EXPOSURE PATHWAY

Surface soil samples collected during the 1990 SSI indicate that elevated concentrations of organic compounds and metals exist in on-site surface soils (E&E 1991). The only apparent soil exposure pathway targets are recreational users. During the site reconnaissance conducted by PRC, several motorcycle trails were observed (see Photographs No. 7 and 8). Potential exposure to soil from this type of recreational use exists because motorcycle riding disturbs soils; therefore, contaminants in the soil could be ingested, inhaled, or absorbed through dermal contact.

The Philo Plant site is fenced except for the ash disposal area, but the site is easily accessible. No Ohio Power Company personnel work at the electrical substation. No workers are employed at the Philo Plant site, and no schools or residences are present within 200 feet of the site.

4.4 AIR MIGRATION PATHWAY

Although no releases of hazardous substances to the air pathway have been documented, this pathway presents a potential risk to recreational users of the Philo Plant site. As discussed in Section 4.3, the site is used for recreational motorcycle riding. There are 212 residents living within 1 mile of the Philo

Plant site. A potential exists for contaminated soil particulates to be inhaled by motorcyclists during summer dry periods.

5.0 SUMMARY

The Philo Plant site is an inactive, coal fired electrical power plant located on the Muskingum River immediately east of the Town of Philo. An SSI conducted by the EPA FIT on February 20 and 21, 1990, revealed contamination of on-site soils and sediments in the Muskingum River with organic compounds and metals. The site contains two primary sources of hazardous substances: an ash disposal area and the two surface impoundments. These sources can affect potential receptors through all four exposure pathways. The municipal drinking water wells for the towns of Philo and Duncan Falls are located within 0.5 mile of the Philo Plant site. Approximately 8,788 people receive their drinking water supplies from municipal and residential wells that are located within 4 miles of the site. Groundwater contamination under the Philo Plant site has not been documented, but the potential for contaminants to migrate to groundwater exists. PRC observed motorcycle trails at the site during the reconnaissance. This type of recreational use disturbs contaminated soils, allowing potential exposure to occur through dermal absorption, ingestion, and inhalation of soil particulates.

REFERENCES

- Ecology and Environment, Inc. (E&E). 1991. Screening Site Inspection Report for the Ohio Power Company Philo Plant (Philo Plant), Site Conducted on February 20 and 21, 1990. Philo, Ohio. March 28.
- Federal Emergency Management Agency (FEMA) 1988. Flood Insurance Rate Map for Unincorporated Areas in Muskingum County, Ohio. June 3.
- Frost and Associates (Frost). 1995. CENTRACTS Report for the Philo Plant Site. January 20.
- Ohio Department of Natural Resources (ODNR). 1995. Letter and Attachment Regarding Fish Catch Estimates for the Muskingum River. From Michael A. Greenlee, Aquatic Biologist, Division of Wildlife. To Dave Harr, PRC Environmental Management, Inc. (PRC). February 22.
- Ohio Environmental Protection Agency (OEPA). 1981. Letter Regarding Status of Philo Plant Site National Pollutant Discharge Elimination System Permit. From Wayne S. Nichols, Regional Director. To Ohio Power Company. June 3.
- OEPA. 1987. Preliminary Assessment of Philo Plant Site. September 23.
- Ohio Power Company. 1975. News Release Regarding Closure of the Philo Plant Site. May 5.
- PRC Environmental Management, Inc. (PRC). 1995a. Record of Telephone Conversation Regarding Drinking Water Intakes along the Muskingum River. Between David J. Harr, Paralegal, and Patricia Archer, ODNR, Muskingum River Parkway. February 14.
- PRC. 1995b. Record of Telephone Conversation Regarding Recreational Use of Muskingum River. Between David J. Harr, Paralegal, and Mike Greenly, ODNR, Division of Wildlife. February 14.
- PRC. 1995c. Logbook Notes for Philo Plant Site Reconnaissance. February 22.
- PRC. 1995d. Record of Telephone Conversation Regarding Town of Philo and Municipal Water Supply. Between Jeff Leto, Environmental Scientist, and Superintendent of the Philo Water Department. March 2.
- PRC. 1995e. Record of Telephone Conversation Regarding the Town of Duncan Falls and Municipal Water Supply. Between Jeff Leto, Environmental Scientist, and Superintendent of the East Muskingum Water Authority. March 2.
- U.S. Department of the Interior (DOI). 1975. 7.5-Minute Quadrangle National Wetlands Inventory Map of Philo and Rokeby Lock, Ohio. March.
- U.S. DOI. 1994. "1994 Federally Listed Endangered, Threatened, and Proposed Species; Ohio."

 April 1.


- U.S. Geological Survey (USGS). 1975a. 7.5-Minute Series Topographic Map of Philo, Ohio, Quadrangle.
- USGS. 1975b. 7.5-Minute Series Topographic Map of Zanesville East, Ohio, Quadrangle.
- USGS. 1992. "Water Resources Data-Ohio, Volume 1, Ohio River Basin. 1991." March.

APPENDIX

SITE RECONNAISSANCE PHOTOGRAPHS

OHIO POWER COMPANY, PHILO PLANT PHILO, OHIO

(Four Pages)



Photograph No. 1


Location: Ohio Power Company, Philo Plant

(Philo Plant)

Orientation: West Date: 02/22/95


Description: One of the two plant cooling

water outfalls




Photograph No. 2 Location: Philo Plant Orientation: South Date: 02/22/95

Description: South surface impoundment and backside of water level regulation tower



Photograph No. 3 Location: Philo Plant Orientation: West Date: 02/22/95


Description: North surface impoundment and front view of water level regulation tower



Photograph No. 4 Orientation: North

Description: Former location of Clearwater Pond


Location: Philo Plant Date: 02/22/95



Location: Philo Plant

Date: 02/22/95

Photograph No. 5
Orientation: North
Description: Former location of western coal pile




Photograph No. 6

Orientation: North

Location: Philo Plant
Date: 02/22/95

Description: Former location of eastern coal pile; residual coal still visible on ground



Photograph No. 7
Orientation: West
Location: Philo Plant
Date: 02/22/95

Description: Former location of northern surface impoundment showing motorcycle trails



Photograph No. 8
Orientation: West
Location: Philo Plant
Date: 02/22/95

Description: Eastern portion of ash disposal area showing motorcycle trails

ATTACHMENT A

SITE INVESTIGATION SOIL AND SEDIMENT SAMPLING LOCATIONS AND ANALYTICAL RESULTS

OHIO POWER COMPANY, PHILO PLANT PHILO, OHIO

(Four Pages)

TABLE A-1
SITE INVESTIGATION SOIL AND SEDIMENT SAMPLING ANALYTICAL RESULTS

Sample Collection Information and Parameters	S1	S2	S3	S4	S5	S6	S7	S8	S9	S10
rarameters			SOIL				SEDIMENT		BGD ^a SOIL	BGD SED
Date	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/21/90	2/21/90
Time	1415	1430	1430	1500	1550	1600	1615	1630	1620	1550
COMPOUND DETECTED (in µg/kg	g) ^{b,c,d}						-	-		
Volatile Organic Compound						<u></u>		 -		
Methylene chloride	30 ^e	240J	110 J	41	170J	19	23	22	ND	ND
Carbon disulfide	2J	5J	2J	3J	3J	3J	ND	ND	ND	ND
Trichloroethene	ND	ND	ND	ND	4J	ND	ND	ND	ND	ND
Tetrachloroethene	ND	ND	ND	ND	14J	ND	ND	ND	ND	ND
Semivolatile Organic Compound										
Naphthalene	130J	1,300	1,301	ND	ND	ND	ND	ND	ND	ND
2-Methylnaphthalene	220J	1,900	154J	ND	ND	ND	ND	ND .	ND	ND
Diethylphthalate	ND	ND	ND	ND	ND	230J	ND	ND	ND	ND
Phenanthrene	130J	980	110 J	ND	ND	ND	100J	ND	ND	ND
Anthracene	ND	130J	ND	ND	ND	ND	ND	ND	ND	ND
Di-n-butylphthalate	97J	170J	ND	100J	ND	150J	130J	130J	ND	ND
Fluoranthene	ND	610J	ND	ND	ND	ND	ND	ND	ND	ND
Pyrene	ND	650J	ND	ND	ND	ND	ND	ND	ND	ND
Benzo(a)anthracene	ND	460J	ND	ND	ND	ND	ND	ND	ND	ND
Chrysene	ND	530J	ND	ND	ND	ND	ND	ND	ND	ND
Bis(2-ethylhexyl)phthalate	120J	270J	95J	ND	ND	290J	150J	ND	ND	ND
Benzo(b)fluoranthene	ND	400J	ND	ND	ND	ND	ND	ND	ND	ND
Benzo(k)fluoranthene	ND	280J	ND	ND	ND	ND	ND	ND	ND	, ND
Tentatively Identified Compound					·	· -		.		
Dichlorodifluoroethane	100J	ND	ND	ND	ND	ND	ND	ND	ND	ND

TABLE A-1 (Continued)

SITE INVESTIGATION SOIL AND SEDIMENT SAMPLING ANALYTICAL RESULTS

Sample Collection Information and	S1	S2	S3	S4	S5	S6	S7	S8	S9	S10
Parameters			SOIL				SEDIMENT		BGD ^a SOIL	BGD SED
Date	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/21/90	2/21/90
Time	1415	1430	1430	1500	1550	1600	1615	1630	1620	1550
ANALYTE DETECTED (values in	mg/kg) ^{c,d,f}									
Aluminum	6,260	17,100	6,950	9,110	27,000	9,540	11,300	4,990	1,550	26,000
Antimony	ND	ND	ND	ND	ND	ND	ND	6.8J	ND	ND
Arsenic	12.43	46.3J	7.43	23.6J	81.2J	10.8J	14.3J	11.73	8.4	29.6
Barium	46.8	238	41.38	97.8	143	120	128	61.8	142	4,160
Beryllium	2.5J	5.0	2.6J	2.9J	8.6	4.2	4.2	3.1J	1.6	5.8
Cadmium	1.7	3.7	1.6	1.18	2.3	2.2	ND	ND	5.2J	7.5J
Calcium	1,160	1,340B	596B	196JB	4,170	15,100	13,600	2,280	17,900	65,300
Chromium	20	50.8	16.3	20	44	23.8	25.4	13.3	32.23J	49.9J
Cobalt	6.0JB	23.1	5.3JB	8.2JB	16.2	22.3	21.3	12.4B	19.1	13.5B
Copper	26.2J	299J	13.8J	35.2J	39.4J	27.8J	26.7J	15.5J	45.8J	52.2J
Iron	23,000	74,800	19,7000	45,300	46,800	29,100	30,500	29,600	40,300	22,300
Lead	10.4	99.7	5.3	15.9	19.7	22.3	22.6	13.1	41.51	46.3J
Magnesium	539B	1,810	404B	1,840	1,460	3,280	3,360	1,180B	3,810	7,450
Manganese	75.5	1,540	26.9	178	359	1,660	1,590	954	955J	24,500J
Mercury	0.11	0.59	0.64	0.13	0.13	0.16	0.15	.013	ND	ND
Nickel	5.48	50.9	5.6B	17.4	37	42.2	41.1	23.7	39.4	30.8
Potassium	1,110	2,630	1,080	1,770	3,390	1,240B	1,610	680B	2,960	4,190
Selenium	ND	3.1	ND	0.608	ND	ND	ND	ND	0.65J	0.33J
Silver	2.1B	2.4B	2.1B	2.2B	1.9B	2.4B	1.9B	1.6B	ND	ND
Sodium	238B	342B	159B	145B	399B	130B	150B	104B	176B	677B
Thallium	1.8B	6.0	1.3B	2.0B	6.4	1.6B	1.9B	1.4B	ND	1.6J

TABLE A-1 (Continued)

SITE INVESTIGATION SOIL AND SEDIMENT SAMPLING ANALYTICAL RESULTS

Sample Collection Information and Parameters	S1	S2	S3	S4	S5	S6	S7	S8	S9	S10
Farameters			SOIL				SEDIMENT		BGD ^a SOIL	BGD SED
Date	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/20/90	2/21/90	2/21/90
Time	1415	1430	1430	1500	1550	1600	1615	1630	1620	1550
Vanadium	13.8	53.8	15.4	35.6	72.4	25.1	27.1	15	38.1J	16.6J
Zinc	26.6	285	20	82.7	107	174	171	89.9	115	185

Source: E&E 1991

Notes:

^a BGD = Background


 $\mu g/kg = Microgram per kilogram$

c Compound Qualifier:

J Indicates an estimated value

Analyte Qualifier:

- J Value is above contract-required detection limit and is an estimated value because of a quality control protocol
- B Value is real but above instrument detection limit and below contract-required detection limit
- d ND = Not detected
- e Shaded value detected above contract-required detection limit (CRDL) and background value is not detected
- f mg/kg = Milligram per kilogram



ATTACHMENT B

CONTRACT LABORATORY PROGRAM CONTRACT-REQUIRED DETECTION LIMITS

(Five Sheets)

Contract Laboratory Program Target Compound List Quantitation Limits

COMPOUND	CAS 1	VATER	SOIL SEDIMENT SLUDGE
Chloromethane	74-87-3	10 ug/L	10 ug/Kg
Bromomethane	74-83-9	10	10
Vinyl chloride	75-01-4	10	10
Chloroethane	75-00-3	10	10
Methylene chloride	75-09-2	5	5
Acetone	67-64-1	10	5
Carbon disulfide	75-15-0	5	5
1,1-dichloroethene	75-35-4	5	5
1,1-dichloroethane	75-34-3		5 5 5 5 5
1,2-dichloroethene (total)	540-59-0	5 5 5	5
Chloroform	67-66-3	5	5
1,2-dichloroethane	107-06-2	5	5
2-butanone (MEK)	78-93-3	10	10
1,1,1-trichloroethane	71-55-6	5	5
Carbon tetrachloride	56-23-5	Š	5
Vinyl acetate	108-05-4	10	10
Bromodichloromethane	75-27-4	5	5
1,2-dichloropropane	78-87-5	5	5
cis-1,3-dichloropropene	10061-01-5		Š
Trichloroethene	79-01-6	5	5
Dibromochloromethane	124-48-1	5	Š
1,1,2-trichloroethane	79-00-5	5	Š
Benzene	71-43-2	5	ζ
Trans-1,3-dichloropropene	10061-02-6	5 5 5 5 5	5 5 5 5
Bromoform	75-25-2	5	Š
4-Hethyl-2-pentanone	108-10-1	10	10
2-Rexanone	591-78-6	10	10
Tetrachloroethene	127-18-4	5	5
Tolene	108-88-3	5	5
1,1,2,2-tetrachloroethane	79-34-5	5	Š
Chlorobenzene	108-90-7	5	5 5 5 5 5
Ethyl benzene	100-41-4	5	ξ
Styrene	100-42-5	5	Š
Xylenes (total)	1330-20-7	· Š	Š

Contract Laboratory Program Target Compound List Semivolatiles Quantitation Limits

			SOIL SEDIHENT
COHPOUND	CAS I	VATER	SLUDGE
Phenol	108-95-2	10 ug/L	330
bis(2-Chloroethyl) ether	111-44-4	10	330 ug/Kg 330
2-Chlorophenol	95-57-8	10	330
1,3-Dichlorobenzene	541-73-1	10	330
1,4-Dichlorobenzene	106-46-7	10	
Benzyl Alcohol	100-51-6	10	330
1,2-Dichlorobenzene	95-50-1	10	330
2-He thy lphenol	95-48-7		330
bis(2-Chloroisopropyl) ether		10	330
	106-44-5	10	330
4-Methylphenol		10	330
N-Nitroso-di-n-dipropylamine		10	330
Hexachloroethane	67-72-1	10	330
Ni trobenzene	98-95-3	10	330
Isophorone	78-59-1	10	330
2-Nitrophenol	88-75-5	10	330
2,4-Dimethylphenol	105-67-9	10	330
Benzoic Acid	65-85-0	50	1600
bis(2-Chloroethoxy) methane	111-91-1	10	330
2,4-Dichlorophenol	120-83-2	10	330
1,2,4-Trichlorobenzene	120-82-1	10	330
Naph thalene	91-20-3	10	330
4-Chloroaniline	106-47-8	10	330
Bexachlorobutadiene	87-68-3	10	300
4-Chloro-3-methylphenol	59-50-7	10	330
2-Methylnaphthalene	91-57-6	10	330
Bexachlorocyclopentadiene	77-47-4	10	330
2,4,6-Trichlorophenol	88-06-2	10	330
2,4,5-Trichlorophenol	95-95-4	50	1600
2-Chloronaphthalene	91-58-7	10	
2-Nitroaniline	88-74-4	50	330
Dimethylphthalate	131-11-3		1600
Acenaphthylene	208-96-8	10	330
2,6-Dinitrotoluene	606-20-2	10	330
3-Nitroaniline		10	330
	99-09-2	50	1600
Acenaphthene	83-32-9 51 30 5	10	330
2,4-Dinitrophenol	51-28-5	50	1600
4-Nitrophenol	100-02-7	50	1600
Dibenzofuran	132-64-9	10	330
2,4-Dinitrotoluene	121-14-2	10	330
Diethylphthalate	84-66-2	10	330
4-Chlorophenyl-phenyl ether	7005-72-3	10	330

Contract Laboratory Program Target Compound List Semivolatiles Quantitation Limits

COMPOUND	CAS #	VATER	SOIL SLUDGE SEDIHENT
Fluorene	86-73-7	10 ug/L	330 ug/Kg
4-Nitroaniline	100-01-6	50	1600
4,6-Dinitro-2-methylphenol	534-52-1	50	1600
N-nitrosodiphenylamine	86-30-6	10	330
4-Bromophenyl-phenylether	101-55-3	10	330
Hexachlorobenzene	118-74-1	10	330
Pentachlorophenol	87-86-5	50	1600
Phenanthrene	85-01-8	10	330
Anthracene	120-12-7	10	330
Di-n-butylphthalate	84-74-2	10	330
Fluoranthene	206-44-0	10	330
Pyrene	129-00-0	10	330
Butylbenzylphthalate	85-68-7	10	· 330
3,3'-Dichlorobenzidine	91-94-1	20	660
Benzo(a)anthracene	56-55-3	10	330
Chrysene	218-01-9	10	330
bis(2-Ethylhexyl)phthalate	117-81-7	10	330
Di-n-octylphthalate	117-84-0	10	330
Benzo(b)fluoranthene	205-99-2	10	330
Benzo(k)fluoranthene	207-08-9	10	330
Benzo(a)pyrene	50-32-8	10	330
Indeno(1,2,3-cd)pyrene	193-39-5	10	330
Dibenz(a,h)anthracene	53-70-3	10	330
Benzo(g,h,i)perylene	191-24-2	10	330

Contract Laboratory Program Target Compound List Pesticide and PCB Quantitation Limits

			SOIL SEDIHENT
COHPOUND	CAS #	VATER	SLUDGE
alpha-BBC	319-84-6	0.05 ug/L	8 ug/Kg
beta-BHC	319-85-7	0.05	8 ug/kg
delta-BHC	319-86-8	0.05	8
gamma-BHC (Lindane)	58-89-9	0.05	8
Beptachlor	76-44-8	0.05	8
Aldrin	309-00-2	0.05	8
Reptachlor epoxide	1024-57-3	0.05	8
Endosulfan I	959-98-8	0.05	8
Dieldrin	60-57-1	0.10	16
4,4'-DDE	72-55-9	0.10	16
Endr in	72-20-8	0.10	16
Endosulfan II	33213-65-9	0.10	16
4,4'-DDD	72-54-8	0.10	16
Endosulfan sulfate	1031-07-8	0.10	16
4,4'-DDT	50-29-3	0.10	16
Hethoxychlor (Mariate)	72-43-5	0.5	80
Endrin ketone	53494-70-5	0.10	16
alpha-Chlordane	5103-71-9	0.5	80
gamma-chlordane	5103-74-2	0.5	80
Toxaphene	8001-35-2	1.0	160
AROCLOR-1016	12674-11-2	0.5	80
AROCLOR-1221	11104-28-2	0.5	80
AROCLOR-1232	11141-16-5	0.5	80
AROCLOR-1242	53469-21-9	0.5	80
AROCLOR-1248	12672-29-6	0.5	80
AROCLOR-1254	11097-69-1	1.0	160
AROCLOR-1260	11096-82-5	1.0	160

CONTRACT LABORATORY PROGRAM TARGET ANALYTE LIST (TAL) INORGANIC DETECTION LIMITS

		Detec	tion Limits
Compound	Procedure	Water (µg/L)	Soil Sediment Sludge (mg/kg)
aluminum	. ICP	200	40
antimony	furnace	60	2.4
arsenic	furnace	10	2
barium	ICP	200	40
beryllium	ICP	5	1
cadmium	ICP	5	1
calcium	ICP	5,000	1,000
chromium	ICP	10	2
cobalt	ICP	50	10
copper	ICP	25	5
iron	ICP	100	20
lead	furnace	5	1
magnesium	ICP	5,000	1,000
manganese	ICP	15	3
mercury	cold vapor	0.2	0.008
nickel	ICP	40	8
potassium	ICP	5,000	1,000
selenium	furnace	5	1
silver	ICP	10	2
sodium	ICP	5,000	1,000
thallium	furnace	10	2
tin	ICP	40	8
vanadium	ICP	50	10
zinc	ICP	20	4
cyanide	color	10	2

ATTACHMENT C

AREA WELL LOGS

OHIO POWER COMPANY, PHILO PLANT PHILO, OHIO

(Eleven Sheets)

WELL LOG AND DRILLING REPORT

PLEASE USE PENCIL OR TYPEWRITER DO NOT USE INK.

State of Ohio DEPARTMENT OF NATURAL RESOURCES Division of Water 1562 W. First Avenue Columbus 12. Ohio

Nº 295303

County June from Cleans	Township	Hanrison	Section of Township			
Owner Okio Pru	(1)		Address Philo Ohio			
Location of property	Silo		Phio			
CONSTRUCTION	DETAILS		BAILING OR PUMPING TEST			
Casing diameter 38" Length Len	gth of scree	- •	Pumping Rate 400 G.P.M. Duration of test 4 hr Drawdown 60 ft. Date 5-1-63 Static level-depth to water 360 ft. Quality (clear, cloudy, taste, odor)			
Depth of pump setting Date of completion 5-1	····		Pump installed by			
WELL LO)G		SKETCH SHOWING LOCATION			
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.			
Cindens Cindens Cindens Gellow Sand Gellow Sand Gellow Sand Gellow Sand	0 Feet 5'0 15'.0 40'-0 55'0 65'0	15-10 20-0 40-0 55-0 65-0	W. S.			
10.	1017		See reverse side for instructions			
Drilling Firm	WA!		Date			

WEL LOG AND DRILLING REMORT

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water

65 S. Front St., Rm. 815 Phone (614) 469-2646 Columbus, Ohio 43215 445147

____TownshipHarrison County Muskinsum _Section of Township. NON RESPONSIVE Owner _ Address Location of property_NON R BAILING OR PUMPING TEST CONSTRUCTION DETAILS (Specify one by circling) using diameter ________ Length of casing 37.1 Test Rate 4 G.P.M. Duration of test..... Drawdown 160 # ft Date ype of screen Length of screen 255_ft. Static level-depth to water____ ype of pump_____ Quality (clear, cloudy, taste, odor) Clear pacity of pump____ 'apth of pump setting___ tate of completion July 20, 1973 Pump installed by_ WELL LOG* NON RESPONSIVE Formations Sandstone, shale, limestone, From To gravel and clay 0 Feet FŁ on Soil 3 12 rown Clay 12 18 ray Clay 18 22 <u>ray Jhale</u> 22 31 ray Sandy Shale 31 37 ray Sand Rock 37 57 ray Sandy Shale 67 62 red Sahle 62 68 rown Sandy Shale 62 68 mowing of Gas 73 68 ray Sandy Shale 73 rown Sandy Shale 84

Drilling Firm Suburban Drilling Company

rev Sandy Shale

84

Address 1950 East Pike, Zanesville, O.

Date July 25, 1973

Signed Signed

*If additional space is needed to complete well log, use next consecutive numbered form.

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio DEPARTMENT OF NATURAL RESOURCES Division of Water

65 S. Front St., Rm. 815 Phone (614) 469-2646 Columbus, Ohio 43215 445148

	Township Ha	rrison	Section of Township
NON RESPONSIVE Owner:			Address NON RESPONSIVE
Location of property	3	NON RESPO	NSIVE,
CONSTRUCTION	DETAILS		BAILING OR PUMPING TEST (Specify one by circling)
ising diameterLen	ngth of casin	g	Test RateG.P.M. Duration of testhrs
ype of screen Ler	igth of scree	n	Drawdown ft. Date
ype of pump			Static level-depth to waterft
apacity of pump		.	Quality (clear, cloudy, taste, odor)
epth of pump setting			
ate of completion			Pump installed by
WELL L	OG*		SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	То	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
	0 Feet	Ft	N.
ray Jandy Shale	92	106	
ray Sand Rock	106	122	
hite Sand Rock	122	202	
Gray Shale	202	217	
ray Sandy Shale	217	225	<u> </u>
ray Shal4	225	236	W. E.
ray Sandy Shale	236	290	
ray Lime Stone	290	296	
ray Jandy Shale	286	318	
hite Sand Rock	318	360	400±
'ater	348		900± 300± 5+0± S.
			当 S.
Drilling Firm Jubu	rban	Her.	Date 7-25-73
Address		e le	St

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio DEPARTMENT OF NATURAL RESOURCES Division of Water

Division of Water 1562 W. First Avenue Columbus 12, Ohio Nº 318886

County Musking Township Hunrison Section of Township

NON RESPONSIVE

Zanesville

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST
Casing diameter			Pumping Rate G.P.M. Duration of test hrs. Drawdown / ft. Date Dec 12-69 Static level-depth to water 7/ ft. Quality (clear, cloudy, taste, odor) 6 Pump installed by SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	То	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
Brown Shale Line stone Chey Shale Soft Chey Shale Coul Sond Kock Chay Sandy Shale Chay Sandy Shale	82 85 87 99 106 98	3 Ft. 7 18 7 75 8 8 7 9 9 10 6 11 4	NON RESPONSIVE
Address Xt. # 2 Willow Dr. Signed Hobert Queles			

a numbered form.

WELL LOG AND DRILLING RELORT

NO CARBON PAPER NECESSARY-

State of Ohio DEPARTMENT OF NATURAL RESOURCES Division of Water

464031

SELF-TRANSCRIBING

65 S. Front St., Rm. 815

Phone (614) 469-2646

Columbus, Ohio 43215 Pronklin Unraham

County Naskingur 7	`ownship	French	Section of Township
OwnerNON RESPONSIV			Address NON RESPONSIVE
Location of propertyNO	N RES	PONS	SIVE
CONSTRUCTION :	DETAILS		BAILING OR PUMPING TEST (Specify one by circling)
Casing diameter 6 5/8 Leng	th of casing	17	Test Rate G.P.M. Duration of testhrs
ype of screen Leng		·	Drawdownft. Date
ype of pump 9 & &			Static level-depth to water 18 ft
Capacity of pump			Quality (clear, cloudy, taste, odor)
Depth of pump setting			
Date of completion			Pump installed by 6 unly
WELL LO	G*		SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	То	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
Surfeee	0 Feet	3 Ft	N.
Sand	3	15	NON RESPONSIVE
Sandstone	15	37	
Water 27 ft.			
		·	V
Drilling Firm Swingle Wat	or Well 1	Drilling	• // ì
Address Reute 7. Zanes	rille. O	10 137	1 Signed Jac Swirfel

WEL' LOG AND DRILLING REPORT

OHIGINAL

NO CARBON PAPER NECESSARY -SELF-TRANSCRIBING State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

536130

SECTION OF TOWNSHIP ADDRESS HEING ON PUMPING TEST CONSTRUCTION DETAILS (specify one by circling) Length of casing. Duration of test. apm Drawdown 29 Date of screen. Length of screen Static level (depth to water). ⇒ of pump, Quality (clear, cloudy, taste, odor) acity of pump. th of pump setting ___ Pump installed by of completion_ WELL LOG* SKETCH SHOWING LOCATION Formations: sandstone, shale, Locate in reference to numbered From Tο state highways, street intersections, county roads, etc. limestone, gravel, clay 0 ft ft

WEI' LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio DEPARTMENT OF NATURAL RESOURCES Division of Water

65 S. Front St., Rm. 815 Phone (614) 469-2646 Columbus, Ohio 43215 462146

n.

County Muskingum	Cownship_E	arrison	s	ection (of Town	nship	
Owner Muskingum River	Park Are	a	Address	P.0	. Box	2806; Zanes	Oh. 1:3701
Location of property Philo	Locktend	ler's Hou	ise. Phi	ilo. (Ohio_	1,3771	
CONSTRUCTION	DETAILS			BA		OR PUMPING T	
sing diameter 6-5/8" Leng	th of casing	31,1	Test Rat	e_2_	G.P	.M. Duration of	test_2_hrs.
pe of screen Slots Len	•		Drawdow	m 73	£	t. Date 11/	3/75
pe of pump			Static le	vel-dept	h to w	ater 21 !	ft.
pacity of pump			Quality ((clear, c	loudy, t	taste, odor)_Cla	ar
pth of pump setting			ļ	·			
ite of completion. 11/6/75	7774.		Pump in	stalled 1	b y		
WELL LO	G*	•	•	SKE	rch si	HOWING LOCA	ATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	State E			eference to number tersections, Cou	
Тор	0 Feet	3 Ft.				N.	
Brown Clay	3	7	}				
Brown Sand	7	17	3	()		Q	
Brown Sand & Sm. Grav	∌ 117	22	ulu	3-	PAM		- \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Brown Sand	22	27	,	20 -	PHM	- (\(\frac{1}{2}\)	. //V KAN
Gray Shale	27	33		 			—
Gray Sandy Shale	33	56	w.0		/	Bridge) E.
Gray Shale	56	65	<u>G</u> -	+	·	-	<u> </u>
Coal Blossom	65	69]	• •	ξ		1 3
Showing of Coal	69	71			Muskirgum	·	
Gray Shale	71	75 TD			3		
1 GPM at 28					/us	a	11
1 GPM at 61:					~	S.	
Drilling Firm Suburban I	rilling	Co., Inc				և. 1975	
Address 1950 East Pik	е		Signed	131	LL 5	1. White	····
Zanesville. O	hin 1/37	01				(TE)	

462148

WELL OG AND DRILLING REPORT

NO CARBON PAPER

NECESSARY-

SELF-TRANSCRIBING

State of Ohio

DEPARTMENT OF NATURAL RESOURCES

Division of Water

65 S. Front St., Rm. 815

Phone (614) 469-2646

Columbus, Ohio 43215

county Muskingum Township Harrison ___Section of Township_ P.O. Box 134 wner Philo Water Works Address Philo Ohio 1 Mile South of Philo on Co. Rd. #6 ocation of property. BAILING OR PUMPING TEST CONSTRUCTION DETAILS (Specify one by circling) 381 ing diameter __10! Test Rate 500 + G.P.M. Duration of test hrs. Length of casing_ Drawdown NBD ft. Date 11/7/75 pe of screen Stainless Length of screen 201 Static level-depth to water 10! pe of pump.... Quality (clear, cloudy, taste, odor)__Clear_ acity of pump__ oth of pump setting___ 11/10/75 te of completion... Pump installed by_ WELL LOG* SKETCH SHOWING LOCATION Formations Locate in reference to numbered Sandstone, shale, limestone, From To State Highways, St. Intersections, County roads, etc. gravel and clay N. 6 Ft 0 Feet qoʻi Brown Clay 6 12 12 18 3rown Silt 23 Brown Sant & Sm. Gravel18 3rown Sand Gray Sand & Water 50 50 Grav Shale Water at 18' Water at 35' W. E. S. Drilling Firm Suburban Drilling Co., Inc. December 16,1975 1950 East Pike Address _ Signed. Zanesville, Ohio 43701

OG AND DRILLING REPORT WELL

PLEASE USE PENCIL OR TYPEWRITER

State of Ohio DEPARTMENT OF NATURAL RESOURCES

Division of Water 1562 W. First Avenue

DO NOT USE INK. Columbus, Ohio 43212 160M Township WAYNE ..Section of Township CONSTRUCTION DETAILS BAILING OR PUMPING TEST Length of casing 98'6 Pumping Rate 200 G.P.M. Duration of test Type of screen Length of screen. Static level-depth to water Type of pump. Quality (clear, cloudy, taste, odor). Capacity of pump. Depth of pump setting ... Date of completion...... 2 Pump installed by WELL LOG* SKETCH SHOWING LOCATION **Formations** Locate in reference to numbered Sandstone, shale, limestone, From To State Highways, St. Intersections, County roads, etc. gravel and clay N. 105 Ft 0 Feet NEW School ROEMER WELL w. See reverse side for instructions Drilling Firm Signed

the Line

WELL LOG AND DRILLING REPORT

No. 295303

					•			
County_	MUSKINGUM	Townsl	nip	HARRISON	Section of Township			
Owner	OHIO POWER			Address	PHILO, OHIO			
Location	of property		PHILO,	OHIO	•	-		
•								
	CONSTRUCTION DETA	ATLS		BAI	LING OR PUMPING TEST			
Casing d	38 x 26 liameterLene	gth of cas	sing 55	Pumping rate	400	G.P.M.		
	screen Layre Leng					Hrs.		
Type of	pump_			_ Drawdown 16	ft. Date 5-1-63			
Capacity	of pump 400) gpm		_ Static level	- depth to water 38	Ft.		
Depth of	pump setting			Quality				
Date of	completion 5-	L - 63		_ Pump install	ed by			
	WELL LOG			SKE	ICH SHOWING LOCATION			
Formatio	n .	From	То		N.			
Top soil Cinders Sand & g Yellow S Yellow S Clay	gravel clay sand	0 5 15 20 40 565	5 15 20 40 55 65 66	. A	s.	E.		
Drilling	Firm Layne (hio			Date 6-4-63			
Address	Co	olumbus, C).		Copied by RH (6/	7/63)		

WELL LJG AND DRILLING REPO

LEASE USE PENCIL

OR TYPEWRITER

DO NOT USE INK.

Drilling Firm Buburhan Drilling Co.

Address 1950 E. Pike, Zanesville, Ohio-

State of Ohio

DEPARTMENT OF NATURAL RESOURCES

Division of Water 1562 W. First Avenue

Columbus, Ohio 43212

Nº 350851

County Muskingum Township Blue Rock Section of Township Owner Corp. of Philo Address Philo, Ohio Location of property Philo, Ohio CONSTRUCTION DETAILS BAILING OR PUMPING TEST Pumping Rate 30 G.P.M. Duration of test hrs. asing diameter 5". Length of casing 491 Drawdown 18 ft Date June 11, 1066 ype of screen.....Length of screen.... Static level-depth to water_______8_ft. ype of pump.____ Quality (clear, cloudy, taste, odor) Clear apacity of pump_____ epth of pump setting..... Date of completion June 11, 1966 Pump installed by.... WELL LOG* SKETCH SHOWING LOCATION **Formations** Locate in reference to numbered To From Sandstone, shale, limestone, State Highways, St. Intersections, County roads, etc. gravel and clay 0 Feet 5 Ft. op ZANESVILL and, Silty 17 rown Sand rown Sand & Gravel 32 40 ray Sand & Gravel-40 roken Sand Rock 45 ine Gray Sand & Gravel 45 48 ray Sandy Broken Sand ock. 48 49 ire Clay 49 51 W. Water @ 10'-Test Well) E. *5.8* See reverse side for instructions

Date June 14, 1966

Signed B. H. White

with inte



WELL LOG AND DRILLING REPORT

County Muskingum	_Townshi	p Ha	rrison Section of Township
Owner Ohio Power Co.			Address Philo, Ohio
Location of property Pi			
` /	•		
CONSTRUCTION DETAI	LS		BAILING OR PUMPING TEST
Casing diameter 13 Length	of casi	ng 52'	Pumping rate 300 G.P.M.
Type of screen Braskength	of scre	en 151	Duration of test 10 Hrs.
Type of pump Turbine	•		Drawdown 5 ft. Date 12-13-55
			Developed capacity 600 GPM at 19 DD
<u></u>			Static level - depth to water 40'6" Ft.
			· · · · · · · · · · · · · · · · · · ·
Date of completion			Pump installed by Ohio Power Co.
WELL LOG	ΙΤ		SKETCH SHOWING LOCATION
D			
Formation	From	To	/ / N.
p Filled Soil		3	
lled cinders			
fore cinder fill	3	28	2.250
and & Gravel	28	65	Bringe Durence Falls
lue Shale	65	67	Philo 1000 Falls
ell to be tested to			
00 GPM for 10 yrs. hen Ohio Power install:			\ \ u.cl(_\)
ump.			3 Elicie Fig.
•			1-41-6
			\s. \\
			Date Nov.2,1955

WELL G AND DRILLING REPO

State of Ohio

OR TYPEWRITER

DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Nº 360970

ORIGINAL

Division of Water 1562 W. First Avenue Columbus, Ohio 43212

County Muskingum 7	ownship Ha	arrison	Section of Township		
Owner Village of Phi	10,	<u> </u>	AddressPhilo, Ohio		
Location of property 4 Mil					
CONSTRUCTION 1	DETAILS	**************************************	BAILING OR PUMPING TEST		
using diameter 10 ⁿ Leng	_		Bailed 60 G.P.M. Duration of test hrs. Drawdown 7 ft. Date		
ype of pump		·	Static level-depth to water		
apacity of pump epth of pump setting			Quality (clear, cloudy, taste, odol)		
ate of completion June 24			Pump installed by SKETCH SHOWING LOCATION		
WELL LO	G*				
Formations Sandstone, shale, limestone, gravel and clay	From	То	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.		
nd & Gravel	0 Feet	36Ft.	N.		
3 Ft. Bridge in Bottor			W. E. See reverse side for instructions		
Drilling Firm Suburban Dr	illing C	0.	Date June 26, 1967		
Address 1950 E. Pike. Za	nesville	, Ohio	Signed B. H. White		

" du truit

WELL LOG AND DRILLING REPORT



NO. 96560

•			
County Muskingum	Townsh	p Harr	rison Section of Township 31
Owner Philo Village Co	rp.		Address Philo ,Ohio
Location of property 400	¹ S. o	f Philo	Corp.limits near Co. Rd. #5
•	•	-	
CONSTRUCTION DETAI	LS		BAILING OR PUMPING TEST
Casing diameter 10 "Length	of cas	ing 701	Pumping rate 75 G.P.M.
Type of screenhnsonLength	of scre	een 10	Duration of test 38 1/2 Hrs.
60 slot Type of pump Deming Tu	rbine		Drawdown 19 ft. Date
Capacity of pump 50 GP**			Developed capacity 75 GPM
Depth of pump setting 7	01		Static level - depth to water 52 Ft.
· · · · · · · · · · · · · · · · · · ·			Pump installed by
Date of completion			Tump Installed by
WELL LOG	·		SKETCH SHOWING LOCATION
Formation	From	To	Sec. 31
Fine Sand & Loam	0	47	
Sand & Fine Gravel	47	50	
Fine Sand	50	65	Phild
Sand & Fine Gravel	65	80	W. CORP. E.
Total depth 80°			(C) • Well
			R
			C#
			s:
Drilling Firm S.M.E	bersba	ch	Date July 18,1952
Address 2195 East	Pike Z	anesvil	le, Ohio Copied by j.c.

WELL ' OG AND DRILLING REPORT

DO NOT USE INK.

State of Ohio DEPARTMENT OF NATURAL RESOURCES Division of Water 1562 W. First Avenue, Columbus, Ohio 43212

mir Nº 350882

Owner			Address
Location of property	e South c	r Philo	; Chic- Co. 7d. 49
CONSTRUCTION	DETAILS	_	BAILING OR PUMPING TEST
sing diameter 10" / Len	gth of casing	· /]]	Pumping Rate 140 G.P.M. Duration of test
pe of screen 1 /0" Sictalen	-		Drawdown O ft. Date
pe of pump			Static level-depth to waterft
pacity of pump	*********		Quality (clear, cloudy, taste, odor)
pth of pump setting			***************************************
ate of completion July 3	<u> </u>		Pump installed by
WELL LO	OG*		SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	То	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
and 3 Gravel	0 Feet	4OFt.	N.
(Water at 10 Ft.)			W. Print III
			S. See reverse side for instructions

nurseful



94539

NO._

WELL LOG AND DRILLING REPORT

Owner_ Village	of Phile	o.Ohio		Address Water Works
				hilo Corp. line
			, <u> </u>	
CONSTRUC	TION DETAI	LS		BAILING OR PUMPING TEST
Casing diemeter	10 " Length	of cas:	ing 53	Pumping rate 194 G.P.
_				Duration of test 14 H
	 ,			Drawdown 8 ft. Date
				
				Developed capacity 200 GPM
	 			Static level - depth to water 26 F
Date of completi	on	<u> </u>		Pump installed by ML Dutro
				1
WEL	L LOG			SKETCH SECURNG LOCATION
Formation	~	From	To	n.
Soil		0	10	
d		10	61	a_{11}
	†			Philo CARP Line
				1/2 m
- ,				W E.
-				(F) 200'
•				2
				Q2/
,			•) s.
·				

WELL LOC AND DRILLING REPORT

State of Ohio

DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES
Division of Water

1562 W. First Avenue

Nº 345935

Sounder Misting Strange	•	Uzyys «	A Section of Township
			Address Phila Lie
			W. River + 1 1/2 Mi South of P. 555
CONSTRUCTION	DETAILS	مو	BAILING OR PUMPING TEST
ing diameter 24 7 16 Len pe of screen Brown Len pe of pump Dac P Well pacity of pump Tost path of pump setting 52	gth of scree	20'	Pumping Rate 200 G.P.M. Duration of test 25 hrs. Drawdown /2 ft Date Nov. 12-19:5 Static level-depth to water /9 ft Quality (clear, cloudy, taste, odor)
e of completion N-V			Pump installed by Bob Harrold
WELL LO)G*		SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	То	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
Lay + Stines	0 Feet	18 Ft.	N.
Exel + Send	18	27	
and + Grayet	27	34	
sud	36	95	F. 555
and + Grarel	45	47	T. Solids 1239
Arid	47	50	i), solved 200 Sulfate 206 E.
AUD + GrAYEL	50	67	W. Fa 5.78 PH 7.6 ///
			1/2
			B+ CO.
			S. See reverse side for instructions
Orilling Firm The Chin	Drilli	ize Cs	Date JAN 10-1949
iddress MESSILLON	Laic		Signed Offilming The

Homeryal

WELL LCG AND DRILLING REPORT



193903 County <u>Muskingum</u> Township Earrison Section of Township 5 Owner Philo Village Address Philo Ohio Location of property On E side of Co. Rd #6 approx 1 i S of Philo O BAILING OR PUMPING TEST CONSTRUCTION DETAILS Casing diameter 10 " Length of casing 54 Pumping rate 225 G.P.M. Type of screen WW Length of screen 8 Duration of test 26 hrs. Type of pump Turbine Drawdown 13 ft. Date 3-19-57 Capacity of pump 150 GPM at . 315 Headeloped capacity 225 GPM by pump Depth of pump setting 49' Static level - depth to water 25 ft. Date of completion 3-15-57 Pump installed by Driller to test well and WELL LOG SKETCH SHOWING LCCATION Formation Frcm To Philo VIIIALE Sandy Loam 0 5 Brown Sand & Gravel 5 52 Gray Sand & Gravel 52 60 W. Water after 261 Drilling Firm R.C. Ramsey Date 3-30-57 Address Rt.6 Zamesville, Ohio Copied by j.c.

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water

65 S. Front St., Rm. 815 Phone (614) 469-2646 Columbus, Ohio 43215 No. 401673 Designeted #8 well

מתני במועצות unty Missing	rownship_	(١٥-١:٩٥١)	Section of Township 2
mer Chis Fores Million	- Coro		Address
cation of property. 50' 5)	1 .F M.	יונטבעני רי	ven 18 miles Took Ab TST
CONSTRUCTION :	DETAILS		BAILING OR PUMPING TEST (Specify one by circling)
of screen Francisco Lenguist of pump 130 h of pump setting of completion.	th of screen	, <i>20'</i>	Test Rate 1000 G.P.M. Duration of test hrs. Drawdown 13 ft. Date 10/10/10. Static level-depth to water ft. Quality (clear, cloudy, taste, odor) Pump installed by
WELL LO	G*		SKETCH SHOWING LOCATION
Formations and stone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
ાં	0 Feet	8 Ft.	morphis : N.
Sand Gaveld Sterier	ક	30'	TH 253
ND, grovel action.	30	<i>\$9'</i>	Nen C 4 124
AND Y ATO TEL SOME Close	38'	471	CL 102 Fe 4.8
Soudy ground	47'	67'	Rt 555
			A / / / /
		· 	18 / 3
			1'Ami (-3')
			
	·		* 50' 7 1
·	·		
			phio force S.
illing Firm The Char D.	Co		Date /190000 15.1471
idress Missillin 0	_		Signed

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

2GW

WATER ANALYSIS

-DC8(10/1		Sa sec.		ounty <u>Muski</u>	
		er 1970	Point of coll. 120 on pump	Diam (in.)
Jaseu to (it) Date	Owner	Oldo Per	ro Alloy, Conton, Ohio		
reatment WBF Sand and gravel, L	7-57	· wi 13	.6 ft. below land Yield	Use <u>Ind</u> 1000	ustrial
			surfice		
emp (°C) Appear wh	20, 1972	В	y Davo Jolio		
lemarks		·			
	mg/l	me/l		_mg/l	me/l
Silica (SiO ₂)	9.6	-	Bicarbonate (HCO ₃)	208	3.41
Aluminum (Al)			Carbonate (CO ₃)	0	.00
Iron (Fe) (uz/l)	2633				,
iongamese (Mn) (ug/1)	1200		Sulfate (SO ₄)	130	2.71
			Chloride (Cl)	120	3.33
			Fluoride (F)	•5	•03
Calcium (Ca)	100	4.99			. •
Magnesium (Mg)	23	1.89	Nitrate (NO3)	.0	.93
Sodium (Na)	60	2.61	Nitrate (NO3-N)	•0	
Potassium (K)	6.0	.15			
Mark to the first of					
<u>rotal</u>	je vr	9.64	Total		9+53
		-		The state of the s	
		mg/l			
		A. 7.	Specific conductance (micromhos at 25°	C)	922
Dissolved solids: Calculated		555	рH		17.5
Residue on evaporation at 180°C		592	Calair		1
Fardness as CaCO3		370	Color		
Noncarbonate		173			
		-	•		
				:	·

UNITED

TES DEPARTMENT OF THE INTERIGEOLOGICAL SURVEY

2GW

WATER ANALYSIS

	sec. 9)(ountyHusk	ingum
drillad		Point of coll 700	Diam (in	.)
Owner	Unknoun	"Trailer wall"	Dame	
	WI	Vield	Use	3010
en collClo				
20, 1972	B	y <u>Dave Johe</u>		
				· · · · · ·
mg/l	me/l		mg/l	me/l
13		Bicarbonate (HCO ₃)	279	4.57
•		Carbonate (CO ₃)	0	.00
24,550			· · · · · · · · · · · · · · · · · · ·	
2,200	-	Sulfate (SO ₄)	670	13.95
	14	Chloride (Cl)	6.0	.17
		Fluoride (F)	1.0	.05
			vi. vi.	
573	11.98			
75	6.17	Nitrate (NO ₃)	.0	.00
27	1.17	Nitrate (Mg-N)	.0	
2.9	.07			
	1, 185			
editer et al 1990.	19.39	Total		18.74
				i pera
•	mg/l			· · · · · · · · · · · · · · · · · · ·
			C)	1,533
4.0	1,200	рН		7.2
	1,310	Color		0, 11,
	910	C0101		
	<u> </u>			
	drilledOwner en collCle 20, 1972 tmping 10 ri mg/l 13 24,000 2,200 240 75 27 2.9	Miled Wile Wile Owner Wile Wile Owner State Owner Owner	Depth (ft) Down Chinom, "Trailer well" WL Yield Yield Point of coil Chinom, "Trailer well" Yield Point of coil Chinoma Yield Yield Point of coil Chinoma Yield Point Yield Point Point Point Yield Point Point	Depth (ft) Diam (in D